



LEVIN PORTER ARCHITECTS

3011 NEWMARK DRIVE 0: 937.224.1931
MIAMISBURG, OHIO 45342 F: 937.224.3091
www.levin-porter.com
Levin Porter Associates Inc. dba Levin Porter Architects

ADDENDUM

ADDENDUM NO. 02

August 6, 2018

Boonshoft Museum of Discovery Do Lab and Restrooms

**LEVIN PORTER ASSOCIATES, INC
3011 NEWMARK DRIVE
MIAMISBURG, OHIO 45342**

LPA PROJECT NO. 74507.00

TO ALL BIDDERS:

This addendum including all items listed hereinafter, shall become a part of the documents, shall be taken into account in preparing the Proposal, and shall become a part of the Contract. The work under each branch shall be in accordance with the original specifications unless excepted in this Addendum.

This Addendum consists of 2 pages plus no attachments:

ITEM NO. 1: CONTRACTOR QUESTIONS:

- 1.1 Is owner buying Permit?
 - A. Owner is paying for the Permit.
- 1.2 Is Bid bond required?
 - a. YES - Reference Specification Section 00 00 04-Instructions to Bidders
- 1.3 Is Performance Bond required?
 - a. NO - Reference Specification Section 00 00 04-Instructions to Bidders
- 1.4 Are cabinets listed the only one we can use?
 - a. NO – cabinets by another manufacturer meeting the Specification / matching the specified units can be provided.
- 1.5 Are we buying new Toilet accessories or reusing existing?
 - a. Reference Specification Section 102800 Toilet Room Accessories for information on Toilet Accessories.



- 1.6 Is carpet for stage tile or roll goods if tile what reducers are we using?
 - a. Do-lab Drawing A-1.3; FINISH SCHEDULE:
CPT-1 is a broadloom sheet carpet, not carpet tile
- 1.7 With the broadloom carpeting on the SCI Theater seating area, do you require any nosings or should everything just be figured wrapped & waterfalled?
 - a. Wrapped & waterfalled, no nosing at the carpeted seating.
- 1.8 The spec for the restroom bullnose is 3x6 to match the 6x6 tiles. In discussing with Daltile, they said that the 3x6 bullnose is a made-to-order (read expensive) product, but there is a 2x6 bullnose that is readily available. Is the 2x6 an acceptable substitute?
 - a. YES
- 1.9 Toilet Partitions are NEW CORRECT?
 - a. YES - Reference Specification Section 102113 Toilet Compartments
- 1.10 The door going into the office in the Do Lab is the only door on this project, yet we have no idea what type it is or what hardware is needed.
 - a. Provide a new painted full flush hollow metal door (minimum thickness of 0.032 inch) and full profile welded frame (minimum thickness of 0.042 inch) at the door between Office 137 and Storage 136. Reuse existing hardware

END OF ADDENDUM NO. 02